




FIELD NOTE: ALL BOLTED CONNECTIONS SHALL BE TIGHTENED TO THE SNUG TIGHT CONDITION. THIS MAY BE ATTAINED BY FEW IMPACTS OF AN IMPACT WRENCH OR THE FULL EFFORT OF A MAN USING AN ORDINARY SPUD WRENCH. (STEEL IS TO BE IN FIRM CONTACT WITH EACH OTHER)

MOMENT CONNECTIONS SYMBOLIZED BY A  SHALL BE INSTALLED PER AISC "SLIP CRITICAL" TYPE CONNECTION.

[illegible]